Annex F

Investigation Reports

Annex F-1

Investigation Report for June 2023

Investigation Report of CEMS Exceedances

Date	1 – 30 June 2023
Time	Continuous monitoring throughout June 2023
Monitoring Location	Continuous Environmental Monitoring System (CEMS)
Parameter	Various emission parameters of the Cogeneration Units (CHPs) and Ammonia Stripping Plant (ASP)
Exceedance Description	 Continuous monitoring was carried out at the CAPCS, CHP and ASP throughout the reporting period using the CEMS. According to the EM&A Manual, exceedance is considered if the emission concentration of the concerned pollutants is higher than the emission limits stated in Tables 2.2, 2.3 and 2.5 of the EM&A Manual (Version F) for CAPCS, CHP and ASP respectively. The concentration of the concerned air pollutants were monitored on-line by the CEMS. Exceedances of various emission parameters were recorded on the CEMS including: NOx and SO₂ from the CHP1; NOx and SO₂ from the CHP2; NOx and SO₂ from the CHP3; and NOx, SO₂ and NH₃ from ASP. The Contractor has investigated the cause of the exceedances and identified that: The exceedances of NO_x and SO₂ from CHPs, and the exceedances of NOx, SO₂ and NH₃ from ASP occurred due to system instability.
Action Taken / Action	The Contractor investigated the reason for the exceedances and
to be Taken	arranged Remedial Works and Follow-up Actions (see below).
Remedial Works and	The Contractor has arranged the CHP supplier to inspect, analyse
Follow-up Actions	and improve CHP performance in July 2023. Improvement
	recommendation will be provided once the report is completed.
	The Contractor has also arranged cleaning and repairing of the ASP in July 2023 to restore the treatment efficiency of the ASP.

Prepared by: Alex Khawaja Waheed, MT Representative

Date 28 November 2023

Investigation Report of Discharged Sample Exceedances

Date	9 June 2023
Monitoring Location	Outlet Chamber of the Effluent Storage Tank
Parameter	Total Nitrogen, Total Phosphorus
Exceedance Description	1. According to EM&A Manual, the monitoring of the effluent
	discharge from the outlet chamber of the Effluent Storage
	Tank and Petrol Interceptors shall be carried out monthly and
	bi-monthly, respectively, under Section 21 of the Water
	Pollution Control Ordinance (WPCO) license. Exceedance is
	considered if the concentration of discharged effluent sample
	from the Effluent Storage Tank and Interceptors is higher
	than the discharge limits stated in Part B2 of the WPCO.
	Exceedances of discharge parameter was recorded during the
	monitoring of effluent discharge from the outlet chamber of
	the Effluent Storage Tank.
	2. The Contractor has investigated the cause of the exceedances
	and found that the exceedance of Total Nitrogen and Total
	Phosphorus from the effluent discharge from the outlet
	chamber of Effluent Storage Tank was potentially caused by
	SBR condition had not stabilized after previous cleaning
	event.
Action Taken / Action	The Contractor investigated the reason for the exceedance. New
to be Taken	effluent sample has been taken on 11 July 2023.
Remedial Works and	The Contractors has arranged action to increase bacteria activities.
Follow-up Actions	Increasing activated sludge volume and extended continuous
	aeration is ongoing to assess the effectiveness.

Prepared by: Benny Lam, MT Representative
Date 13 July 2023

Annex F-2

Investigation Report for July 2023

Investigation Report of CEMS Exceedances

Date	1 - 31 July 2023
Time	Continuous monitoring throughout July 2023
Monitoring Location	Continuous Environmental Monitoring System (CEMS)
Parameter	Various emission parameters of the Cogeneration Units (CHPs)
	and Ammonia Stripping Plant (ASP)
Exceedance Description	 Continuous monitoring was carried out at the CAPCS, CHP and ASP throughout the reporting period using the CEMS. According to the EM&A Manual, exceedance is considered if the emission concentration of the concerned pollutants is higher than the emission limits stated in Tables 2.2, 2.3 and 2.5 of the EM&A Manual (Version F) for CAPCS, CHPs and ASP respectively. The concentrations of the concerned air pollutants were monitored on-line by the CEMS. Exceedances of various emission parameters were recorded on the CEMS including: NOx and SO₂ from the CHP1; NOx, SO₂ and HCl from the CHP3; and NOx, SO₂, NH₃, and HCl from ASP. The Contractor has investigated the cause of the exceedance and identified that: The exceedances of NO_x and SO₂ from the CHPs, HCl from CHP3 and the exceedances of NOx, SO₂, NH₃, and HCl from ASP occurred due to system instability.
Action Taken / Action	The Contractor investigated the reason for the exceedances and
to be Taken	arranged Remedial Works and Follow-up Actions (see below).
Remedial Works and	The Contractor has arranged the CHP supplier to inspect,
Follow-up Actions	analyse and improve CHP performance in Aug 2023 based
	on final reports of the quality assurance level 2 test (QAL)
	for the CEMS calibration. Improvement recommendation
	will be provided once the report is received.
	The Contractor has also arranged cleaning of the ASP in
	August 2023 to restore the treatment efficiency of the ASP.

Prepared by: Benny Lam, MT Representative

Date 8 Aug 2023

Investigation Report of Discharged Sample Exceedances

Date	31 July 2023
Monitoring Location	Outlet Chamber of the Effluent Storage Tank
Parameter	Total Nitrogen, Total Phosphorus
Exceedance Description	 According to EM&A Manual, the monitoring of the effluent discharge from the outlet chamber of the Effluent Storage Tank and Petrol Interceptors shall be carried out monthly and bi-monthly, respectively, under Section 21 of the Water Pollution Control Ordinance (WPCO) license. Exceedance is considered if the concentration of discharged effluent sample from the Effluent Storage Tank and Interceptors is higher than the discharge limits stated in Part B2 of the WPCO. Exceedances of discharge parameter was recorded during the monitoring of effluent discharge from the outlet chamber of the Effluent Storage Tank. The Contractor has investigated the cause of the exceedances and found that the exceedances of Total Nitrogen and Total Phosphorus were due to fresh seeding sludge injection to the SBR system in mid-July 2023, bacterial activities of second stage treatment for the complete removal cycle was lagging behind which result in incomplete bacterial reaction of the effluent.
Action Taken / Action	The Contractor investigated the reason for the exceedance.
to be Taken	
Remedial Works and	The Contractors has arranged action to increase bacteria activities.
Follow-up Actions	Increasing activated sludge volume and extended continuous
	aeration is ongoing to assess the effectiveness.

Prepared by: Benny Lam, MT Representative

Bate 8 Aug 2023

Annex F-3

Investigation Report for August 2023

Investigation Report of CEMS Exceedances

Date	1 – 31 August 2023
Time	Continuous monitoring throughout August 2023
Monitoring Location	Continuous Environmental Monitoring System (CEMS)
Parameter	Various emission parameters of the Centralised Air Pollution Control Unit (CAPCS), Cogeneration Units (CHPs) and Ammonia Stripping Plant (ASP)
Exceedance Description	 Continuous monitoring was carried out at the CAPCS, CHP and ASP throughout the reporting period using the CEMS. According to the EM&A Manual, exceedance is considered if the emission concentration of the concerned pollutants is higher than the emission limits stated in Tables 2.2, 2.3 and 2.5 of the EM&A Manual (Version F) for CAPCS, CHPs and ASP respectively. The concentrations of the concerned air pollutants were monitored on-line by the CEMS. Exceedances of various emission parameters were recorded on the CEMS including: Total Odour (NH3 and H2S) from the CAPCS; NOx and SO2 from the CHP1; NOx, SO2, and HCl from the CHP2; NOx, SO2 from the CHP3; and NOx, SO2 and NH3 from ASP. The Contractor has investigated the cause of the exceedance and identified that: The exceedances of NOx, SO2, and HCl from the CHPs, as well as the exceedances of NOx, SO2 and NH3 from ASP occurred due to system instability. The exceedances of Total Odour (NH3 and H2S) from the CAPCS were caused by the filter being blocked and the sensor head being clogged with moisture.
Action Taken / Action	The Contractor investigated the reason for the exceedances and
to be Taken	arranged Remedial Works and Follow-up Actions (see below).
Remedial Works and Follow-up Actions	 The Contractor has arranged the CHP supplier to inspect, analyse and improve CHP performance in September 2023 based on final reports of the quality assurance level 2 test (QAL) for the CEMS calibration. Improvement recommendation will be provided once the report is received. The Contractor has also arranged cleaning of the ASP in September 2023 to restore the treatment efficiency of the ASP. Finally, the Contractor has arranged for the calibration of the NH₃ and H₂S sensors of the CAPCS in September 2023.

Prepared by: Alex Khawaja Waheed, MT Representative

Date 11 September 2023